



West Coast Reduction Ltd.

Phone: 1.855.867.3389

ORDER# 20134325 TS



1-TS20134325

SERVICE DATE: 10/22/20

Service Location Account #: 91673

THE ONE TWENTY  
8037 120TH STREET, #120  
DELTA BC V4C 6P7  
CANADA

Site Contact:

CHEF MICHAEL  
Email: michael@one20pub.com  
Phone: 604 5913519

Water Solid FOG

Trap ID: TRAP1 Location : BACKDOOR Location Description : OUTSIDE OF KITCHEN BACK DOOR IN GROUND UNDER METAL LID


Before Service



After Service



Estimated FOG Analysis



Volume (LT): 380

Bylaw Compliance: No

Repairs Required: Yes

Frequency: Every 4 Months

Repair Details: Flow Plate:Seized,Gasket:Required,Lid:Drill and Tap Required,

#### CSA Standard for Maintenance

The Canadian Standards Association's (CSA) Maintenance of Grease Interceptors B481.4-07 states that a grease interceptor should never be serviced less than once every 4 weeks (28 days) and more frequently if the combined depth of **FOG (Fats, Oils and Grease)** and solids exceeds 25% of the liquid volume of the grease interceptor.

Service Technician: MAVROS, ANDREAS

Truck: 1TKC1471

Patrick

10/22/20