



7505655

Grease Interceptor Report

Installations, Maintenance and Cleaning

Account

| | | |
|---|--|---|
| Account <u>Brioche Ristorante and Catering</u> | Date of Service <u>10/31/2025</u> | Time <u>06:30h</u> |
| AHJ (Authority having jurisdiction) <u>Eduardo Bilardello</u> | Service Interval Annually <input type="checkbox"/> Quarterly <input type="checkbox"/> Bi-Annually <input type="checkbox"/> Monthly <input checked="" type="checkbox"/> | |
| Address Line 1 <u>103 Colombia St,</u> | Inspection Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> | Cleaned Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| Address Line 2 _____ | Manufacturer <u>NA</u> | |
| City <u>Vancouver</u> | Province <u>BC</u> | Postal Code <u>V6A 3Z8</u> |
| Model(s) <u>NA</u> | Size (Gallons): <u>250</u> | |
| Phone (Business) <u>(604) 682-4037</u> | Total Liquid Collected <u>264</u> | |
| Phone (Mobile) <u>(604) 760-1272</u> | Interceptor Location <u>Basement</u> | |
| Fax _____ | | |

Mark appropriate: Pass Fail. All FAIL answer shall be explained in comments. All failures shall be the responsibility of the authority having jurisdiction to repair or replace at their expenses. Any additional repair costs are not included with this inspection, unless otherwise stated.

Pre-Service


 --

Answers / Comments

| | |
|--|--|
| Grease Interceptor is accessible to service | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| Inspected condition of the Grease Interceptor before service | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| Grease Interceptor is functional prior to service. | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| FOG's do not consume more than 25% of the Interceptor (If fail recommend increasing service intervals) | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| There are no leaks found in the Grease Interceptor(s) | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| Condition of the gaskets and seals | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| After Service | |
| Grease Interceptor has been properly cleaned | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| Rate of flow is sufficient | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| Condition of the Grease Interceptor after service | Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/> |
| Any issues have been reported to the AHJ | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| Service tag has been issued or updated | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| Location of service tag: On Interceptor | |
| Is a return visit required to complete repairs? | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |

Approx. percentage of grease & solids in relation to the Grease Interceptor.

GI (Basement)



Notes:

I state that the information on this form is correct at the time and place of inspection. All equipment was tested in conformance with applicable codes equal to or beyond manufacturer specifications. At the time indicated above, equipment inspected or serviced was left in operational condition except as noted in comments. I understand that under municipal city bi-laws a copy of this report is to remain on premises for a period no less than 2 years.

Owner/Authorized Agent: Eduardo Bilardello Date: 10/31/2025 Technician: Alex J. Collins

October 31, 2025



Before



Before



After



After