



Grease Interceptor Report

Account

Account	Edo Japan			
Date of Service	11/07/2025		Time	08:30h
AHJ (Authority having jurisdiction)	Gurinder (Sakaar) Singh			
Service Interval	Annually	Quarterly	Bi-Annually	Monthly <input type="checkbox"/>
Address Line 1	P3-02, 45585 Luckakuck Way			
Inspection	Yes <input type="checkbox"/>	No	Cleaned	Yes <input type="checkbox"/> No <input type="checkbox"/>
Address Line 2				
Manufacturer	Watts			
City	Chilliwack	Province	BC	Postal Code V2R 1A1
Model(s)	DI-210			
Phone (Business)	(604) 392-8035			
Size (Gallons)	100			
Phone (Mobile)	(778) 882-4100			
Total Liquid Collected	102 gal			
© 2025 Grease Ducks Ltd				
Fax				
Interceptor Location	Kitchen Floor			
Mark appropriate: <input type="checkbox"/> Pass <input type="checkbox"/> Fail. All FAIL answers shall be explained in comments. Failures are the responsibility of the AHJ to repair/replace at their expense. Additional repair costs are not included with this inspection unless otherwise stated.				