



DISTRICT OF NORTH VANCOUVER
FIRE AND RESCUE SERVICES

FIRE SAFETY INSPECTION FORM

BUSINESS NAME: Gilaneh Grillhouse
ADDRESS: 222 Pemberton Ave

DATE: 11/02/2016
CONTACT: Shahrani Pouriaei

A fire safety inspection was done at the property described above.
The following conditions were noted and require correction immediately.

Actions Required: Please see violations and comments below.

Status:

- | | |
|--|----------------|
| 1 BCFC 6.5.1.6.(2)(b) Emergency lights require annual testing. | UNSATISFACTORY |
| 2 BCFC 6.3.1.2.(1) Annual fire alarm servicing and testing required. | UNSATISFACTORY |
| 3 BCFC 2.6.1.9.(2) Exhaust and fire protection systems shall be inspected and maintained as per NFPA 96. | UNSATISFACTORY |
| 4 NFPA 10-8.4.1 Repair / replace damaged extinguishers. | UNSATISFACTORY |
| 5 FIRE DEPARTMENT ACCESS | UNSATISFACTORY |
| 6 ' | ' |
| 7 ' | ' |

Comments:

- 1 - Some emergency light packs are not working at all in dining room and corridor.
- 2 - Fire Alarm panel has no service tag
- 3 - Kitchen Exhaust hood and wet chem system are due for semi-annual service/cleaning. K Class extinguisher needs a seal on pin.
- 4 - Portable fire extinguishers are due for 6 yr hydro service. Repair or replace extinguishers
- 5 - 2nd floor access required for inspection. Please arrange access to floor.

You are hereby notified that the above conditions shall be corrected **within 28 days**. Failure to correct the above noted violations could render the owner or occupier liable to penalties provided for under The District of North Vancouver Bylaws and/or regulations pursuant to the Fire Services Act.

Note: 2012 BC Fire Code Div C 2.2.1.1.(1) "Unless otherwise specified, the owner or the owner's authorized agent shall be responsible for carrying out the provisions of this code."

Received By:

met
STAFF ON
SITE

Title: Employee

Issued By:

Title: Howard Weatherstone, Lieutenant

Phone: 604-990-3673